


**FTDI USB**  
 Use FT\_PROG utility  
 and set CBUS3 as  
 GPIO

**XILINX  
 JTAG**

Xilinx Virtual Cable with FT220X



MECHANICAL

- M100 Screw M3x12
- M101 Screw M3x12
- M102 Screw M3x12
- M103 Screw M3x12
- M104 Washer M3
- M105 Washer M3
- M106 Washer M3
- M107 Washer M3
- M108 Standoff M3x5
- M109 Standoff M3x5
- M110 Standoff M3x5
- M111 Standoff M3x5
- M112 JUMPER

MECHANICAL

Derived form XVC\_FT220X01A  
 F1 - added fuse  
 D1-D3 - changed to SMD Reverse Mount  
 L1 - smaller PCB Footprint

Firma		Author MIHO	
<b>MLAB</b>			
Size A4	Project Name XVC_FT220X02A	Schematic Name Main Page	Rev 1.00
Date: Friday, March 22, 2013	Sheet 1 of 1		